

SPX Corporation 5885 11th Street Rockford, IL 61109-3699 USA Tech. Services: (800) 477-8326 Fax: (800) 765-8326 Order Entry: (800) 541-1418 Fax: (800) 288-7031 **Parts List for:** 


RH1508

Internet Address: http://www.powerteam.com

## MODEL B DOUBLE-ACTING, HOLLOW CENTER HYDRAULIC CYLINDER

Max. Capacity: 149.7 Tons at 10,000 PSI





Note: Shaded areas reflect last revision(s) made to this form.

Sheet No. 1 of 1

Rev. 1 Date: 22 Mar. 1999



A DANGER: To help avoid possible serious personal injury or death,

In the event that the cylinder retract port is ever restricted or plugged, a double-acting cylinder relief valve will help prevent excessive pressure from building in the cylinder. DO NOT attempt to adjust or service this relief valve! If oil leakage is detected from this relief valve, discontinue use of the cylinder immediately and contact Power Team Technical Services. Only Power Team Authorized Hydraulic Service Centers should service this relief valve.

Item No.	Part No.	No. Req'd	Description	
110.	140.	nequ	Description	
1	*250197	1	O-ring (7.50 x 7.25 NITRILE)	
2	*250198	1	Washer, Backup (7.50 x 7.25)	
3	58047	1	Nut, Retainer (8-12; NOTE: Torque to 590 Ft. Lbs.)	
4	*250203	1	Wiper, Rod (6.50 x 6.00 URE)	
5	350066	1	Insert, Threaded	
6	*250200	1	T-seal (6.50 x 6.00 x .36 L)	
7	59225OR9	1	Handle, Cylinder Lift	
8	*250202	1	Wiper, Rod (4.69 x 4.25 URE)	
9	*250201	1	T-seal (7.50 x 7.00 x .36 L)	
10	*250199	1	T-seal (4.63 x 4.25 x .27 L)	
11	*10858	1	O-ring (4.50 x 4.25 NITRILE)	
12	*19171	1	Washer, Backup (4.50 x 4.25)	
13	65992	1	Body, Cylinder	
14	420040	1	Pipe, Stand	
15	10556	1	Screw, Set (1/4-20 x 1/4; See NOTE below)	
16	9796	2	Coupler, Quick Cylinder Half	
17	64054	1	Rod, Piston	То
				Drawi
	PARTS INCLUDED BUT NOT SHOWN			
	*37782	1	Decal, Warning	
	351882	1	Decal, Tradename (Power Team)	

Part numbers marked with an asterisk (\*) are contained in Repair Kit No. 300583.

NOTE: Cylinders built after 1-1-99 do not use this set screw to lock the standpipe and cylinder body together. Loctite 242 is used on last 2-3 standpipe threads only!

Note: Shaded areas reflect last revision(s) made to this form.

Refer to any operating instructions included with this product for detailed information about operation, testing, disassembly, reassembly, and preventive maintenance.

Items found in this parts list have been carefully tested and selected. **Therefore: Use only genuine Power Team replacement parts!** 

Additional questions can be directed to our Technical Services Department.