
Form No. 101809



SPX Corporation 5885 11th Street Rockford, IL 61109-3699 USA Tech. Services: (800) 477-8326 Fax: (800) 765-8326 Order Entry: (800) 541-1418 Fax: (800) 288-7031 Parts List for:

RH203V

Internet Address: http://www.powerteam.com



Item	Part	No.	
No.	No.	Req'd	Description
1	28611	1	Insert
2	205122	2	Upper Spring Lock
3	28608	2	Spring Retainer
4	14244	1	Extension Spring
5	28607	1	Gland Nut
7	† 19241	1	T-seal & Backup Rings (Smooth side of Backup Ring must be against seal.)
8	34111	1	Piston Rod
9	†19239	1	T-seal & Backup Rings (Smooth side of Backup Ring must be against seal.)
11	34157	1	Cylinder/Standpipe Ass'y (Unpainted)
12	9796	1	Ram Half Coupler w/Dust Cap
13	205121	2	Lower Spring Lock
PARTS INCLUDED BUT NOT SHOWN			
	† 205724	1	Decal (Viton)
	202173	1	Trade Name Decal
	† 19526	1	Seal (For coupler)

Part numbers marked with a daggar (†) are contained in Repair Kit No. 300222.

Refer to any operating instructions included with this product for detailed information about operation, testing, disassembly, reassembly, and preventive maintenance.

Items found in this parts list have been carefully tested and selected. Therefore: Use only genuine Power Team replacement parts!

Additional questions can be directed to our Technical Services Department.